UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.: 09/741,616 Page 1 of 1

DATED: August 13, 2008

INVENTOR(S): John, Lizy, Srinivasan, Srivatsan

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 8

Line 65, "Bit b0=0, Bit bl=0, ...and Bit b15=0" should read --..Bit b0=1, Bit b1=1, Bit b2=1, Bit b3=1, Bit b4=0, Bit b5=1, Bit b6=0, Bit b7=1, Bit b8=1, Bit b9=0, Bit b1 3=0, Bit b14=0, Bit b15=0..--.

Column 9

Line 29, "...by connecting by connecting..." should read --...by connecting...-..
Column 10

Column

Line 52, "...Table I1..." should read --...Table II1...--.